U.S. Department of Transportation

800 Independence Ave., S.W Washington, D.C. 20591

Federal Aviation Administration

Transmittal Letter 15-08

February 27, 2015

PREPARED BY THE PRODUCT SUPPORT GROUP, AJV-34 (AVAILABLE ON THE WEB AT HTTP://NFDC.FAA.GOV)

The enclosed Standard Instrument Approach Procedures, Departure Procedures/Takeoff Minimums and Fix Actions are effective as indicated.

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA, LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:

AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DATE	SUBJECT
2-Apr-15	AR	Corning	Corning Muni	5/9339	02/11/15	VOR/DME-A, Amdt 2

FDC 5/9339 4M9 IAP CORNING MUNI, CORNING, AR. VOR/DME-A, AMDT 2... CHART NOTE: PROCEDURE NA AT NIGHT. CHART NOTE: HELICOPTER VISIBILITY REDUCTION BELOW 1 SM NOT AUTHORIZED. CHANGE ALTIMETER SETTING NOTE TO READ: WHEN LOCAL ALTIMETER SETTING NOT RECEIVED USE WALNUT RIDGE ALTIMETER SETTING. DELETE PLANVIEW NOTE: NOPT FOR ARRIVAL ON ARG VORTAC AIRWAY RADIALS 149 CW 297. CHART PLANVIEW NOTE: PROCEDURE NA FOR ARRIVALS ON ARG VORTAC AIRWAY RADIALS 016 CW 089.

THIS IS **VOR/DME-A, AMDT 2A**. 1502041825-PERM